

- It's BEST to re-dump the drive after update and use that fw as source.
- For everyone that has already updated and wants to use his old files, manual load the 1.9 fw and press spoof, for everyone else auto-load works correctly.
- When spoofing from old fw to new one it **IS** normal to say serial info not copied and ID strings not copied to target.
- For the ones that want to flash their 74850C liteon drives to stock use the 1a000 file. Don't ask why, just do it.
- If when loading the LT+ 1.9 says stock, you are using old version of JungleFlasher, please download and use the latest one.
- For those who want to dump a 0272 drive, please read the Read Before Using text in the OFW folder of 0272 in Lite-on (Slim).
- All that have consoles that NOT have been updated use the pre folder to flash to stock, update and then use the Post folder to flash to LT+ 1.9
- And again, if your console has the new update, use the Post folder.
- ALL updated phat lite-on drives can **only** be dumped with MRA or PhatKey method. Any other drive can be dumped exactly as before.
- It is highly recommended to flash to stock fw first so you avoid possible update failures, then do the 13146 update and flash the LT+ 1.9.
- LT+ 1.1 on all drives except hitachi are not Xbox live safe on 13146 update so we recommend DO NOT flash back to LT+ 1.1. Instead use the new LT+ 1.9 fw
- The 13146 update, writes stock fw on all drives except hitachi, all phat lite-on drives now become 02510C, 9504 become 0272, all benq drives become 04421C and Samsung are just patched.
- 13146 update can't retrieve your key if you don't have it on drive.
- X360key will be banned on Xbox live as Microsoft can easily detect it.
- All kits are for one and only one drive.
- Because Microsoft can enable the write protect on 9504 drives ,which now are 0272, whenever they want , it is recommended to use the kits as you can control if they are write protected or not.
- Because compatible motherboards for 0225 and 0401 are hard to find as they are very rare and these drives are very picky, it is recommended to get an x360usb as it is confirmed to be working 100% with these drives.